



Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name:

Work Order Type: Weatherization

Audit Name: MADISON

CLIENT INFORMATION

Client Name:

Address:

Client ID:

Alt. Client ID: 16016SW-0124

AGENCY INFORMATION

Agency: SWHRA

Agency Phone: (731) 989-5111

Address: 1574 White AVE
Henderson, TN

Fax:

Email Address:

Agency Contact: Murley, Rickey

Work Phone:

Cell Phone:

Email Address:

Company Name & License Number: _____

Contractor's Signature: _____

COMMENT

NOTICE:

All work performed and material must meet all requirements as stated in the Southeast Weatherization Field Guide. It is the contractor's responsibility to pull all necessary permits required for the town or county where the work is being performed. No change order work shall be done until the change order has been approved and signed. If heater is required no air sealing should be done before heater is installed.

731-326-7168

Client Name:

Work Order (Bid Form)

DOE Weatherization Assistant

Client ID:

Work Order Name:

Version 8.5.0

Alt. Client ID: 16016SW-0124

Report Run On: 5/14/2010

Page 1 of 5

Measures

Measure 1 Infiltration Redctn				Components						Inspected
Comment										<input type="checkbox"/>
				Estimated			Actual			
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1	Construction Materials/Hardware	Seal off back room off laundry room	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
2	Labor	Labor	Hour		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
3	Construction Materials/Hardware	Seal ceiling to wall in laundry room, Seal pipes behind washer and dryer and wall to floor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
4	Labor	Labor	Hour		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
5	Construction Materials/Hardware	Seal where plwood was installed and seal ceiling above water heater, Seal furnace closet	Each		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
6	Labor	Labor	Hour		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
7	Construction Materials/Hardware	NW bedroom closet repair wall behind tub and seal vent pipe top and bottom. Living room repair floor 4x8 approx area	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
8	Labor	Labor	Hour		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
9	Construction Materials/Hardware	Hall bath repair floor approx 3x3 area, Seal pipes under kitchen sink, Seal fireplace in ironing room	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
10	Labor	Labor	Hour		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
11	Construction Materials/Hardware	Rrepair hall wall to floor, Seal chimney in living room, Seal dinning room floor to wall	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	
12	Labor	Labor	Hour		<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	

Client Name:

Work Order (Bid Form)

DOE Weatherization Assistant

Client ID:

Work Order Name:

Version 8.5.0

Alt. Client ID: 16016SW-0124

Report Run On: 5/14/2010

Page 2 of 5

Other Detail

Measure Sub Total:

Sub Total:

Field Notes:

Measure 2 DWH Pipe Insulation

Components

Inspected

Comment

Estimated

Actual

#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	DHW Pipe Insulation	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>

Other Detail

Measure Sub Total:

Sub Total:

Field Notes:

Client Name:

Client ID:

Alt. Client ID: 16016SW-0124

Work Order (Bid Form)

Work Order Name:

Report Run On: 5/14/2010

DOE Weatherization Assistant

Version 8.5.0

Page 3 of 5

Measure 3 DWH Tank Insulation				Components			Inspected		
Comment									
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Hot Water Equipment	DHW Tank Insulation	Each	1					
2	Labor	Labor	Each	1					
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 4 Attic Ins. R-30				Components A1			Inspected		
Comment									
				Estimated			Actual		
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Insulation	Attic Insulation - Blown Cellulose - Add 10 inches	SqFt	1958					
2	Labor	Labor	Hour	1958					
3	Miscellaneous Supplies	Install attic access cover	Each	1					
3	Labor	Labor	Hour						
Other Detail									
Measure Sub Total:							Sub Total:		
Field Notes:									

Measure 5 CO Monitor is Needed				Components				Inspected	
Comment								<input type="checkbox"/>	
				Estimated				Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	CO monitor	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>
Field Notes:									

Measure 6 Smoke Detector is Needed				Components				Inspected	
Comment								<input type="checkbox"/>	
				Estimated				Actual	
#	Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1	Health and Safety Items	Smoke detector	Each	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
2	Labor	Labor	Hour	1	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Other Detail									
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>	<input type="text"/>
Measure Sub Total:						<input type="text"/>	Sub Total:		<input type="text"/>
Field Notes:									

Work Order Grand Total:

Grand Total: